
## EXHIBIT D

## ASSIGNED LAND AND REAL PROPERTY IMPROVEMENTS (CONCESSION FACILITIES)

## Land Assigned

Land is assigned in accordance with the boundaries shown on the following map[s]:



## **Real Property Improvements Assigned**

The following real property improvements are assigned to the Concessioner for use in conducting its operations under this Contract:

| Asset<br>Number | Asset Description                       | Asset<br>Type | Quantity | UOM  | Date<br>Built | Historic<br>(Yes or No) | Minimum<br>Insurance<br>Replacement<br>Value (IRV)* |
|-----------------|---|---------------|----------|------|---------------|-------------------------|---|
| 64644           | LeConte Lodge Water<br>System, LLW      |               | 1        | SQFT | 1984          | Ν                       | \$136,656   |
| 64698           | LeConte Lodge<br>Wastewater System, LES |               | 1        | SQFT | 1984          | Ν                       | \$140,140   |

| 72041 | LeConte Guest Cabin<br>Number 4                        | 131   | SQFT | 1943 | Ν | \$32,060  |
|-------|--|-------|------|------|---|-----------|
| 72065 | LeConte Guest Cabin<br>Number 5                        | 152   | SQFT | 1943 | Ν | \$35,833  |
| 72068 | LeConte Guest Cabin<br>Number 6                        | 152   | SQFT | 1943 | Ν | \$35,833  |
| 72072 | LeConte Guest Cabin<br>Number 7                        | 131   | SQFT | 1943 | Ν | \$32,060  |
| 72075 | LeConte Guest Cabin<br>Number 8                        | 131   | SQFT | 1943 | Ν | \$32,060  |
| 72076 | LeConte Guest Cabin<br>Number 9                        | 131   | SQFT | 1943 | Ν | \$32,060  |
| 72082 | LeConte Guest Cabin<br>Number 10                       | 152   | SQFT | 1943 | Ν | \$35,833  |
| 72083 | LeConte Employee<br>Quarters "Honeymoon<br>Cabin"      | 165   | SQFT | 1940 | Ν | \$32,576  |
| 72085 | LeConte Dining Room /<br>Kitchen / Quarters            | 1,783 | SQFT | 1964 | Ν | \$438,847 |
| 72087 | LeConte Two Bedroom<br>Lodge "New Lodge"               | 638   | SQFT | 1984 | Ν | \$116,463 |
| 72088 | LeConte Three Bedroom<br>Lodge "Old Lodge"             | 836   | SQFT | 1933 | Ν | \$145,378 |
| 72228 | LeConte Three Bedroom<br>Lodge "East Lodge"            | 581   | SQFT | 1986 | Ν | \$107,089 |
| 72247 | LeConte Duplex Employee<br>Quarters "New Ritz"         | 390   | SQFT | 1990 | Ν | \$80,522  |
| 72284 | LeConte Employee<br>Quarters / Showers "Wash<br>House" | 565   | SQFT | 1962 | Ν | \$116,536 |
| 72292 | LeConte Employee<br>Quarters "The Shack"               | 181   | SQFT | 1960 | Ν | \$38,661  |
| 72301 | LeConte Generator House                                | 119   | SQFT | 1999 | Ν | \$8,439   |
| 72310 | LeConte Storage & Tool<br>Shed "Woodshed"              | 481   | SQFT | 2004 | Ν | \$24,511  |
| 72316 | LeConte Employee<br>Quarters "Tack House"              | 195   | SQFT | 1958 | Ν | \$42,454  |
| 72327 | LeConte Food Storage<br>Building                       | 720   | SQFT | 1999 | Ν | \$37,820  |
| 72339 | LeConte Employee<br>Quarters "New Duplex"              | 577   | SQFT | 2001 | Ν | \$109,486 |
| 72349 | LeConte Pit Toilet                                     | 73    | SQFT | 1986 | Ν | \$34,017  |
| 72445 | LeConte Flush Toilets                                  | 100   | SQFT | 1986 | Ν | \$43,950  |
| 98260 | LeConte Water Pump<br>Building                         | 44    | SQFT | 2004 | Ν | \$3,183   |
| 98261 | LeConte LP Gas System                                  | 1     | SQFT | 1999 | Ν | \$248,221 |
| 98262 | LeConte Solarvoltaic Power<br>System                   | 1     | SQFT | 2004 | Ν | \$26,001  |

\* The aggregate total of the Minimum Insurance Replacement Values for the individual assets listed in the tables above indicates only the minimum real property insurance coverage that the Concessioner must procure and maintain in effect during the term of the Contract. Notwithstanding the inclusion of Minimum Insurance Replacement Values for the individual assets listed in the tables above, the Concessioner has an obligation, under Section 12(d)(1) of the Contract, to repair or replace damaged or destroyed Concession Facilities and personal property utilized by the Concessioner in the performance of its obligations under the Contract, regardless of cost. The Concessioner therefore should evaluate the various risks of loss to the Concession Facilities assigned to it under the Contract, including the risk of catastrophic loss, and procure real and personal property insurance it deems sufficient to cover those risks. The Concessioner will not be relieved of its obligations under Section 12(d)(1) of the Contract because its insurance proceeds are not sufficient to repair or replace damaged or destroyed property.

\*\* Please note: The lack of value for an asset in the column for Insurance Replacement Value does not relieve the Concessioner of its obligation to insure the asset according to the terms of this Contract.

Approved, effective \_\_\_\_\_

By \_\_\_\_\_ Mark A. Foust Regional Director Interior Region 2 National Park Service