



Glenbrook Quarry Restoration and Dam Removal


Restoring Natural Process in the
Phillip Burton Wilderness





Drakes Estates Development Proposal





Glenbrook Dam, 1960



Kenneth and Gabrielle Adelman
www.californiacoastline.org



Time series – Dam overview
Pre-restoration



Time series – Dam overview
Initial clearing of west arm



View of Breach



Time series – Dam overview
Temporary Crossing complete
Initial clearing of east arm



Temporary crossing, culverts allow tidal flow through site during construction

National Park Service
Point Reyes National Seashore





Time series – Dam overview
Excavation to grade, east to west



Time series – Dam overview
Removal of temporary crossing



Time series – Dam overview
Excavation complete



Time series - Dam overview
At high tide



Time series view across breach
East arm pre-restoration



Time series view across breach
Initial excavation of top 8 feet



Time series view across breach
Excavation to grade



Time series view across breach
Removal of temporary crossing



Time series view across breach
Excavation complete



Time series view across breach
High Tide



Time series view across breach
High Tide



Time series view across breach
High Tide

